Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00155

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513					
Exit Meeting Contact: John Sigler	Total Man Days: 1					
Pipeline Safety Representative(s): Kevin Hecker						
Company Representative to Receive Report: Michael Fuller	Emailed Date:					
Company Representative's Email Address: mfuller2@ameren.com	06/05/2015					

Inspection Summary

Inspection Type	Location	ICC Analyst	Inspection Unit(s)	Man Day(s)	Inspection Date(s)	Contact(s)
Standard Inspection - Field Audit	Alexis	Kevin Hecker	Shanghai Storage	1	3/24/2015	John Sigler

Statement of Activities

On March 24, 2015, a representative from the Illinois Commerce Commission conducted a Field Audit at Ameren Illinois Company's Shanghai Storage facility located in Alexis, IL. The purpose of this audit was to determine compliance with applicable IL Adm. Codes and the Code of Federal Regulations adopted via IL Adm. Part 590.

Exit Statement

INSPECTION FINDINGS

Standard Inspection - Field Audit

Issues(s) Found:

[NO ISSUES FOUND]

Notice Of Amendment(s) Found:

[NO NOAS FOUND]

Notice Of Violation(s) Found:

[NO NOPVS FOUND]

PAST INSPECTION FINDINGS

Issue(s) Corrected:

[NO ISSUES CORRECTED]

Notice Of Amendment(s) Corrected:

[NO NOAS CORRECTED]

Illinois Commerce Commission Pipeline Safety Pipeline Safety Report

Inspection #: 2015-P-00155

Notice of Violations(s) Corrected:

[NO NOPVS CORRECTED]